


# DART SERVICE INSTRUCTION


TO AMEND INSTALLATION DRAWING D2046901 REV. 6

REF. TCCA STC: SH92-30, FAA STC SR00911NY (204B)  
REF. TCCA STC: SH92-54, FAA STC: SR00937NY (205A/A-1/B)  
REF. TCCA STC: SH92-55, FAA STC: SR00938NY (212/412)  
REF. TCCA STC: SH92-56, FAA STC: SR00939NY (214B/B-1)  
REF. EASA STC: EASA.IM.R.S.01285

**PURPOSE:**

The purpose of this service instruction is to replace the MS16997-22 screw used in the latch assembly with MS16997-24 screw.



CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01	
APPROVED  BY: <u>D. SHEPHERD (DE # 02)</u>	
DATE:	11.10.26
CERT. NO.:	SH92-30-54/-55/-56
ISSUE NO.:	3/4/3/3

A	NEW ISSUE		XDF	11.10.26	
REV.	DESCRIPTION			BY	DATE
DESIGN	XDF		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	REV. A	SHEET 1 OF 1
DRAWN	XDF				
CHECKED			DRAWING NO. DSI 9581		
MFG. APPR.	N/A				
APPROVED			TITLE SCREW REPLACEMENT	SCALE NTS	
DE APPR.					
DATE	11.10.26		COPRIGHT © 2011 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		